APPLICAB	LE STAN	DARD									
0	PERATING		−25 °C TO +85	°C		RAGE TEMPERATUR		RE	-10 °C TO +60) °C	
	TEMPERATURE RANGE		10 050 W DO 10	20 1/	RANGI	E					
_	VOLTAGE		AC 350 V , DC 49	90 V	4001	101DLE	04515			_	
C	URRENT		5 A	ILICV		ICABLE	CABLE			_	
		T	SPECI	IFICA	HOI	<i>N</i> 2				1	
ITEI		TEST METHOD				REQUIREMENTS				QT	AT
CONSTRU		ı			-					1	1
GENERAL EXAMINATION		VISUALLY AND BY MEASURING INSTRUMENT.				ACCORDING TO DRAWING.				X	X
MARKING		CONFIRMED VISUALLY.								Χ	X
ELECTRIC CHARA										1	
CONTACT RESISTANCE		CONTACT SHALL BE MEASURED AT DC 1 A				4 mΩ MAX.				X	X
INSULATION RESISTANCE		500 V DC.				1000 MΩ MIN.				Х	Х
VOLTAGE PROOF		1000 V AC. FOR 1 min.				NO FLASHOVER OR BREAKDOWN.				X	X
MECHANIC	CAL CHA	RACTE	RISTICS								
CONTACT INSERTION AND WITHDRAWAL FORCES		BY STEEL GAUGE.				INSERTION AND WITHDRAWAL FORCES : -N .				-	-
CONNECTOR INSERTION AND		MEASURED BY APPLICABLE CONNECTOR.				INSERTION AND WITHDRAWAL FORCES : 70 N MAX.				X	_
WITHDRAWAL FORCES		LOCKING DEVICE WITH UNLOCK.								<u> </u>	
MECHANICAL OPERATION		2000 TIMES INSERTIONS AND EXTRACTIONS.				CONTACT RESISTANCE: 8 mΩ MAX.				Х	_
VIBRATION		FREQUENCY 10 TO 55 Hz, SINGLE AMPLITUDE 0.75 mm,				①NO ELECTRICAL DISCONTINUITY OF 10 μs. ②NO DAMAGE, CRACK AND LOOSENESS OF PARTS.				Х	_
SHOCK		m/s ² , AT 10 CYCLES, FOR 3 DIRECTIONS. 490 m/s ² DURATION OF PULSE 11 ms AT 3 TIMES				①NO ELECTRICAL DISCONTINUITY OF 10 μs.					
onoon		FOR 6 DIRECTIONS.				②NO DAMAGE, CRACK AND LOOSENESS OF PARTS.				X	_
ENVIRONI	MENTAL	CHAR/	ACTERISTICS							1 .	1
DAMP HEAT		EXPOSED AT 40 °C, 90 TO 95 %, 96 h.				① INSU	ATION RE	SISTA	NCE: 100 MΩ MIN		
(STEADY STATE)		EALOSED AT 40 C, 30 TO 33 70, 30 TI.				(AT DRY).				X	_
,						② NO DAMAGE, CRACK AND LOOSENESS OF PARTS.					
RAPID CHANGE OF TEMPERATURE		TEMPERATURE $-55 \rightarrow R/T^{(1)} \rightarrow +85 \rightarrow R/T ^{\circ}C$				① INSULATION RESISTANCE: 100 MΩ MIN				Х	
		TIME 30 \rightarrow 2 TO 3 \rightarrow 30 \rightarrow 2 TO 3 min				② NO DAMAGE, CRACK AND LOOSENESS OF PARTS.				^	-
		UNDER 5 CYCLES.									
CORROSION SALT MIST		EXPOSED IN 5 % SALT WATER SPRAY FOR 48 h.				NO HEAVY CORROSION RUIN THE FUNCTION.				Х	_
DRY HEAT		EXPOSED AT + 85 °C , 96 h.				NO DAMAGE, CRACK AND LOOSENESS OF PARTS.				Х	_
COLD		EXPOSED AT - 55 °C , 96 h.				NO DAMAGE, CRACK AND LOOSENESS OF PARTS.				Х	_
RESISTANCE TO SOLDERING		PLACE SOLDERING IRON (IRON TIP TEMPERATURE +380±				NO DEFORMATION OF CASE OF EXCESSIVE LOOSENESS				Х	
HEAT		1 '				OF THE TERMINALS.					
SOLDERABILITY		PLACE SOLDERING IRON (IRON TIP TEMPERATURE +350±				WETTING ON SOLDER SURFACE.				Х	_
		10°C) AND SOLDER TO SOLDERING POT AREA FOR 3 s.				NO SOLDER CLUSTER.					
SEAL ING (2)		EXPOSED AT	(POSED AT A DEPTH OF 1.8 m FOR 48 h.			NO WATER PENETRATION INSIDE CONNECTOR.				Х	_
AIRTIGHTNESS (2)		APPLY AIR PRESSURE 17.6 kPa FOR 0.5 min TO INSIDE CONNECTOR.			NO AIR BUBBLES FROM CONNECTOR INTERFACE.				X	-	
COUNT	DF	SCRIPTIC	ON OF REVISIONS		DESIG	NED			CHECKED	DA	TE
&					220.0				020.125		
REMARK	1			<u> </u>			APPRO	VED	EJ. KUNI I	15.0	1. 30
NOTES (1) R/T :	ROOM TEMPERA	TURE			ŀ	CHEC		EJ. KUNI I		1. 30	
	NG AND AIRTIG					DESIG		WR. AJIRO		1. 30	
SHALL	. BE TESTED UN	DER MATED CONDITION WITH AN APPLICABLE CONNECTOR.			ł.	DRAWN			WR. AJIRO		, , , 50
11.1. 2	. •.	bified refer to IIS C 5400						VN			1. 30
		ified, refer to JIS C 5402.								1	
Note QT:Qua	alification Tes	t AT:Assurance Test X:Applicable Test			DR	DRAWING NO.			ELC-111098-72-72		
11/2			CATION SHEET	11661		NO.	RM15WTRZB-12P (7))		
	HIR	OSE ELECTRIC CO., LTD.			CODE NO.		CL109-1676-0-72			◮	1/1